

SEL/Gould/Encore Computer Top Level Assemblies

COMPRO can provide or repair the following SEL, Gould, and Encore computer assemblies. This includes assemblies for Encore computer models 32/27, 32/67, 32/77, 32/87, 32/97, and RSX systems.

To request a quote, contact us at **800-936-2673**. You can also fax your request to **321-727-7009** or send an email to info@compro.net.

Note: COMPRO is the authorized Sales, Service, and Repair affiliate of Encore Real Time Computing, Inc. for the U.S. and Encore's exclusive distributor for South America.

<i>Part Number</i>	<i>Description</i>
001-190-000	P/S RTP 5V Assembly
001-92-000	P/S RTP1 Assembly
105-103001-001	2152/2154, Memory Module Assembly, Core, 32KB
105-103002-001	2000 Wire-Wrap CPU Assembly
105-103016-001	RTP Serial Interface Assembly
105-103025-001	16KB Memory Module Assembly, 900NS
105-103041-005	Serial Control Assembly
105-103044-001	AC Power Distribution Panel Assembly
105-103044-002	AC Power Distribution Panel Assembly
105-103047-001	Power Distribution Control Panel Assembly
105-103108-001	RS-422 DISTR Assembly
105-103146-002	5/3 Backplane Chassis Assembly
105-103147-001	PDU Assembly, 115V
105-103147-002	PDU Assembly, 230V
105-103220-002	8/0 Backplane Chassis Assembly, PS 230V 50HZ
105-103262-001	AC Assembly
105-103294-004	Tape Drive Assembly
105-103294-006	8MM Cartridge Tape MDL Assembly
105-103309-002	4-Slot RMC Chassis Assembly
105-103312-001	Power Supply Assembly (Contains 269-100100-001 Power Supply)
105-103312-005	P/S MOD 1200W Assembly
106-103327-001	MUXP Printed Circuit Board Assembly, CR, LP, SW
107-103303-005	Blower Sub-assembly
107-103313-004	Power Supply (GPDC) Subassembly
107-103344-003	Power Supply (Case for 269-100040-001)
107-103556-001	Power Supply Subassembly
107-103677-001	Power Supply Assembly (Contains 269-100089-001 Power Supply)
107-103743-001	RMS Chassis Subassembly
107-103746-001	RMC Assembly
107-103747-001	SCSI Adapter Subassembly
107-103865-003	Disc Assembly, 4GB
107-103946-001	PCI-RMS Bridge Printed Circuit Board
119-103294-001	HSDI Modification